


15B151

E.C.O.	REV.	DATE	DWN.	CHK.	APP.	CHANGES



NOTE:  
 1. INSERT ITEMS 15A5032 & 15A5033  
 AND SWAGE OVER AS SHOWN  
 2. INSERT ITEM 15A153 INTO 15B155 &  
 SWAGE OVER  
 3. ASSEMBLE ALL OTHER ITEMS AS SHOWN

CD201	15R100	1					
JOB NO.	NEXT ASS'Y	NO. REQ'D					
DO NOT SCALE DRAWING							
UNLESS OTHERWISE SPECIFIED			MATERIAL	DWN.	CHK.	ENG.	APP.
SURFACE ROUGHNESS ✓				J			
FILLETS ✓ R. MAX.							
BREAK ALL SHARP							
EDGES CHAM. MAX.							
ALL DIMENSIONS HELD							
AFTER SURFACE TREATMENT							
DECIMALS ±							
FRACTION ±							
ANGLES ±							
SCALE 2/1							
DWG. NO.	15B151	REV.					